


# Surface Milling

---



1. Lay out and mark all areas to be milled.
2. Mill existing surface to a depth of 2" utilizing machinery designed specifically for this operation.
3. Cut perimeter of areas to produce a vertical face adjacent to stable surface.
4. Clean entire area of repair and dispose of debris offsite.
5. Install specified finish material.

MILLING MACHINE  
GRINDER TEETH

